

The source of the sound in the footunit is the fabric sitting between the actual foot rolling mechanism on each foot and the outer leather padding. To eliminate the sound, you must remove the fabric by following these steps:

1. REMOVE THE OUTER LEATHER PAD BY UNZIPPING THE ZIPPER; ONCE UNZIPPED, BE MINDFUL OF THE AIRBAGS THAT ARE SEATED INSIDE A FLAP ON THE INSIDE OF THE PAD.



Inside of outer
leather pad;
Airbag flap

2. OBSERVE THE FABRIC IN QUESTION. TO REMOVE THE FABRIC, YOU MUST REMOVE 6-8 SCREWS THAT SECURE IT TO THE FOOT. NOTE: THE 4 SCREWS ON THE PERIMETER SECURE THE AIRBAGS IN PLACE. **YOU MUST BE SURE TO SECURE THE AIRBAGS WITH THESE SCREWS WHEN REASSEMBLING OR THEY WILL BECOME CAUGHT IN THE FOOT ROLLER AND BREAK THE UNIT.**

